

Here are the numbers given by Dr. Dave
 Note the variation of the beginning shank dimension.
 It varies from .3868 to .3888". That's too much variation if the same shank was used. This is not easy to measure! The key is accuracy. A .002" difference in this measurement will cause a .04" change in the gap. Is it the receiver taper, measuring process, or repeatability?

